TO: HAROLD JONES

September 21, 1998

FROM: KEITH C WILSON

RE: DIVERSIONS FROM INDIAN CREEK - INKOM AREA

(Gen. area Sec. 28, 32, & 33, T7S, and Sec. 5, & 6, T8S, R36E)

As you instructed me to do I drove up Indian Creek to look for diversions on September 18, 1998. I drove up the Indian Creek road a total of 2.9 miles to a gate across the road. I observed the flow in Indian Creek in several locations along the road.

Site #1: Flow under road @ orchard & holding pond

Site #2: Flow in driveway culvert ≈1.0 miles above site #1.

Site #3: Flow through stockyard ≈1.8 miles above site #1.

Site #4: Flow through culvert ≈2.5 miles above site #1.

It was my observations that the flow from Indian Creek at site one (pond @ orchard) was at least equal to the flow at Site #4. I did not observe any major diversions from the creek.

Keith C. Wilson

Senior Resource Agent

